



Contractor Requirements

1. Current Certificate of Insurance (COI)
2. Updated (less than one year old) Safety Training Checklist for each individual. Safety training must be refreshed at least annually.
3. Current (from current calendar year or December of previous year) 9-panel drug screen showing negative results
4. Comply with Contractor Safety Rules and Regulations (TP-563-00062)
5. If first time on site watch induction video at Security
6. All mobile equipment/vehicles on site must have a flashing light and a backup alarm.
7. PPE Requirements:
 - Hard Hat
 - Hi-viz shirt, vest, or jacket with reflective stripes
 - Safety toe boots. Met-guard required inside Cast House, Cell House, and Cadmium Plant casting area.
 - Long sleeves
 - Long pants
 - Gloves (appropriate to the task) required to be in your possession in all PPE areas, and worn while working with your hands.
 - Safety Glasses with side shields is minimum required eye protection. Certain areas require more protective eye wear per the matrix below.

Task/Condition	Minimum Eye Protection	Examples
Potential exposure to concentrated acid	Chemical Goggles with face shield	Roaster/Acid: All work in acid plant, acid tank farm, loading acid trucks or rail cars.
Potential exposure to leaching solution, purified solution, spent solution	Safety glasses with face shield, or chemical goggles. R- Racal-type respirator satisfies face shield requirement	Leach/Purification and Cadmium Plant: Cleaning launders, flushing screen boxes, collecting solution samples. Cell House: Cell or launder cleaning, working in/on cooling towers, cell house basement area



<p>Potential exposure to hot materials, molten metals, or high-pressure cleaning equipment, when loading/unloading corrosive chemicals, or when grinding</p>	<p>Face shield with safety glasses or goggles</p>	<p>Roaster/Acid: Lancing boiler or working in roaster/boiler regulated area (requires PAPR with integrated face shield). Cast House: Working within 10 feet of molten metal. Cadmium Plant: Working within 10 feet of molten metal. Maintenance: Grinding.</p>
<p>Welding</p>	<p>Welding helmet with safety glasses or goggles</p>	<p>Welding</p>
<p>Potential exposure to a dusty environment or where dust generation is reasonably likely</p>	<p>Safety glasses with full foam rim or chemical goggles that seal to face</p>	<p>Concentrate shed/mix pad/oxide wash, unloading a barge, transloading/handling dry oxide material, Cast House dross handling, cleaning dry material with compressed air, working on dry material conveyors such as boiler drag chain or redlers, working with friable insulation.</p>
<p>Other tasks/conditions not included in other categories where the risk of eye injury or material in the eyes is low</p>	<p>Safety glasses with side shields</p>	